

FOX STONECARPET® COATING AFTER APPLICATION MAINTENANCE INSTRUCTIONS

FOX STONECARPET® coating is a polyurethane resin-based coating. Resin-based coatings become surmountable 24 hours after the application is completed (at 23°C and 50% humidity). It takes its final cure after 7 days.

It can be opened for use 7 days after the use of the materials in the coating and all the steps of the coating are completed.

During this process, the applied place should be protected and heavy loads should not be placed on it.

Floor and wall coatings with **FOX STONECARPET®** coating do not require renewal, repair, etc., if the usage, maintenance and cleaning instructions are followed.

PHYSICAL AND CHEMICAL CLEANING, MAINTENANCE

- 7 days after the **FOX STONECARPET®** coating is done, the first cleaning should be done (after it has cured) with a Karcher brand hard surface cleaning device with brush.
- Thanks to its reverse vacuum feature, it ensures that all possible dust, etc., is cleaned on all porous and non-porous coatings.
- Depending on the frequency of use (more than 200 people per day), brush cleaning is recommended daily or every other day.
- In weekly and monthly maintenance, it is recommended to clean with the same method with liquid soap.
- It is recommended to apply a **FOX PURATHANE® TOPCOAT WB TRANSPARENT GLOSSY/MATTE** top coat protective layer at the first stage of production in order to keep the surface as it was on the first day and for a longer life.

